# **Borth Coastal Protection Scheme Phase 2 – Weekly Report**

Week 22 – ending 24<sup>th</sup> October

| ECC PM:           | Atkins             | Rob Morgan   |
|-------------------|--------------------|--------------|
| Contractor:       | BAM Nuttall        | Ray Jones    |
| CDM Co-ordinator: | Royal HaskoningDHV | Steve Vernon |
| Site Supervisor:  | Royal HaskoningDHV | David Cramp  |

# **Planned Activities**

| Area   | Description  |       |
|--|--|-------|
| Site Compound  | Compound set-up is complete.   | 100%  |
| Beach Access and   | Rock deliveries are complete.  | 100%  |
| Rock Stockpile   |  | 00/   |
| Breakwater 1   | Work yet to commence.  | 0%    |
| Breakwater 2   | Work yet to commence.  | 0%    |
| Breakwater 3   | Work continued on the northern section of Breakwater<br>3.<br>Laying geotextile – 70%<br>Placing Type 3 rock – 64%<br>Placing Type 1 rock – 81%<br>Archaeologists were on site to supervise excavations. | 72.5% |
| Groyne 1   | The Groyne 1 structure was completed this week.<br>Laying geotextile – 100%<br>Placing Type 3 rock – 100%<br>Placing Type 1 rock – 100%  | 100%  |
| Groyne 2   | Structure complete.  | 100%  |
| Beach Nourishment<br>(Phase 2)   | No work undertaken.  | 5%    |
| Beach Nourishment<br>(Phase 1)   | Work completed based on PMI 4. This released approximately 860m <sup>3</sup> of shingle for re-use in Phase 2 nourishment.   | 100%  |
| Breastwork<br>Remedial Work continued on the breastwork remedial along the<br>frontage of the golf course north of Phase 2. Timber ply<br>and (re-cycled) groyne planks from Phase 2 were<br>applied to damaged sections along the breastwork. |  | -     |

# Weather and Tidal Conditions

- Very strong winds up to 30mph and gusts of 60mph on Tuesday 21<sup>st</sup> October. Caused by the aftermath of Cyclone Gonzalo.
- Heavy showers and strong winds throughout the week.
- Spring tides.

# Plant on Site

- 1Nr. P65 Dozer
- 1Nr. 45t tracked excavator with grab
- 3Nr. 45t tracked excavator with bucket
- 1Nr. 24t tracked excavator with bucket
- 4Nr. 35t dumper truck (1 NOT USED)
- 1Nr. Telehandler
- 1Nr. Tractor and Water Bowser
- 1Nr. JCB

#### People on Site

- 3Nr. BAM Staff (Site)
- 5Nr. BAM Staff (Office)
- 9Nr. Plant Operatives
- 6Nr. Labour
- 1Nr. Ceredigion County Council
- 3Nr. Archaeologists

#### Material Approval and Delivery

• Material deliveries are complete.

| Туре                           | Type 1<br>(3-6t) | Type 3<br>(300-1000kg) | 75/40  | Type A<br>(Shingle) | Type B<br>(Shingle<br>Backfill) | Type C<br>(40mm) |
|--------------------------------|------------------|------------------------|--------|---------------------|---------------------------------|------------------|
| Total to<br>week               | 367.52           | 0                      | 0      | 0                   | 0                               | 0                |
| Previously                     | 302037.26        | 15126.43               | 884.01 | 0                   | 0                               | 0                |
| Total to<br>date<br>(12.09.14) | 32404.78         | 15126.43               | 884.01 | 0                   | 0                               | 0                |
| QS Total                       | -                | -                      | -      | -                   | -                               | -                |

#### **Planned Activities Next Week**

• Construction to continue on Breakwater 3 at the northern end of the beach.