Borth Coastal Protection Scheme - Weekly Report

Week 19 - ending 20th May

| ECC PM : | Atkins | Rob Morgan |
|-----------------|--------------------|---------------|
| Contractor: | BAM Nuttall | Ray Jones |
| CDM coordinator | Faithful and Gould | Martin Clark |
| Site Supervisor | Royal Haskoning | Alice Johnson |

Planned Activities

| | I famileu | Activities | | |
|--------------------|----------------------|-------------|--|------------|
| Area | | | Description | Completion |
| | Site Compo | ound | Completed. Main number is 01970 871 834. | 100% |
| | Beach Acc | ess North | North Access is complete | 100% |
| | Beach Acc | ess South | Southern access is complete | 100% |
| Groyne 1 | | | Groyne 1 is complete. | 100% |
| | Groyne 2 | | Significant progress and been made on the groyne this week with the under layer complete and a good amount of primary rock placed. | 45% |
| | Breakwater | r 1 | Not Started | 0% |
| Breakwater 2 | | r 2 | The under layer and digging is now complete. | 63% |
| Temporary Causeway | | Causeway | The causeway is being extended towards the area of the reef. | 50% |
| North Reef | | | Not Started | 0% |
| South Reef | | | Not Started | 0% |
| | Shingle Material | Nourishment | Further replacement has been brought in and is currently being stockpiled. | 57% |
| S | Shingle Placement | Nourishment | No further nourishment was placed this week due to work concentrating on other activities. | 23% |
| | Other | | The anchor block has been placed and is identified by a lit yellow special mark. | - |
| | | | | |

Weather and Tidal Conditions

• Windy, cold, and light showers, good tides.

Plant on Site

- 2Nr. Bulldozer (Blade).
- 1Nr. Telly-handler and bowser all week
- 2Nr 360 tracked excavator with bucket
- 3Nr 450 tracked excavator with grab
- 5Nr 35t dumper truck.

People on Site

- 10Nr Bam Staff and Support
- 9Nr Labour
- 12Nr Plant operators
- 3Nr Others

Material approval and delivery

- Replacement and 0.3-1t rock continues to be delivered from Ystrad Murig. 5-100kg stone has started to be delivered from Ystrad Murig.
- Natural shingle is delivered from Cefn Graianog
- Primary 3-6t Armour is delivered from Builth Wells.

| Туре | E - Replacement | C1 - Natural | 5-100kg Stone | 0.3-1t Rock | 3-6t Rock | 6-10t Rock |
|---------------|-----------------|--------------|---------------|-------------|------------|------------|
| 13/5 | 1006.46 | 284.86 | 461.84 | 0 | 105.34 | 0 |
| 14/5 | 19.84 | 85.92 | 209.94 | 0 | 84.88 | 0 |
| 16/5 | 1386.14 | 421.82 | 373.14 | 0 | 83.88 | 0 |
| 17/5 | 1211.72 | 401.08 | 523.58 | 0 | 202.38 | 0 |
| 18/5 | 672.76 | 288.86 | 742.40 | 0 | 265.74 | 0 |
| 19/5 | 686.70 | 296.44 | 699.94 | 0 | 308.14 | 0 |
| Total to week | 4,983.62 | 1,778.98 | 3,010.84 | 0 | 1,050.36 | 0 |
| Previously | 79,627.16 | 12,137.16 | 1,503.17 | 18,427.00 | 16,002.16+ | 50.80+ |
| - | | | | | (3,000) | (42,000) |
| Total to date | 84610.78 | 13916.14 | 4,514.01 | 18,427.00 | 17,052.52 | 42,050.80 |

NB. This is an approximate table and checked tonnages are held by QS.

Planned Activities Next Week

- Near completion of Breakwater 2
- Continue shingle nourishment works on the beach.
- Continue on Groyne 2.
- Push out causeway towards reef.
- Removal of Groynes

Public Relations

• Ysgol Craig yr Wylfa have completed their safety posters and logos and winners have been chosen.