Borth Coastal Protection Scheme - Weekly Report

Week 59 – ending 26th February

ECC PM:AtkinsRob MorganContractor:BAM NuttallRay JonesCDM coordinatorFaithful and GouldMartin ClarkSite SupervisorRoyal HaskoningAlice Johnson

Planned Activities

Area		Description	Completion
Site Compound		Completed. Main number is 01970 871 834.	100%
Beach Access North		North Access is complete Some replacement and rock fragments remain. No further work	100% place 80% tidy up
Beach Access South		Southern access is complete.	100%
Groyne 1		Groyne 1 is complete.	100%
Groyne 2		Groyne 2 is complete	100%
Breakwater 1		Some further work on Breakwater 1 done.	95% core 19% top
Breakwater 2		Breakwater 2 is complete.	100%
Temporary Causeway North Reef		Temporary causeway is complete. South link has been removed. Limited work due to concentrating on removing causeway.	100% build ~55% removal 98% bedding 100% core
South Reef		South Reef is complete	73% top 100% bedding 100% core 100% top
Shingle Material	Nourishment	Shingle deliveries are now complete.	100%
Shingle Placement	Nourishment	No further work	84%
Other		A maritime exclusion zone is now in place around the reef and causeway; the reefs are now marked by the permanent west cardinal.	-

Weather and Tidal Conditions

• Spring tides, mixed weather, some rain, some wind, some waves.

Plant on Site

- 0Nr. Bulldozer (kept onsite)
- 1Nr. Tele-handler and bowser all week
- 3Nr. 450 tracked excavator with grabs
- 1Nr 340 Excavator with griddle bucket
- 2Nr. 35t dumper truck (1 on standby)

People on Site

- 6Nr. Bam Staff and Support
- 7Nr. Labour
- 5Nr. Plant operators

Material approval and delivery

• Rock deliveries complete for the moment.

Type	E – Rep.	C1 - Natural	5-100kg	0.3-1t Rock	0.5-1t	3-6t Rock	6-10t
			Stone		Rock		Rock (Nr.)
Total to week	0.00	0.00	0.00	0.00	0.00	0.00	0.00
Previously	122,699.91	54,667.78	13,419.71	21,916.88	7,755.28	26,680.70	47,915.60
Total to date (14.2.12)	122,699.91	54,667.78	13,419.71	21,916.88	7,755.28	26,680.70	47,915.60
QS Total (22.2.11)	123,940	52,130	15,151	22,202	7,806	25,241	48,274

NB. This is an approximate table and checked tonnages are held by QS.

Planned Activities Next Week

- Remove link causeway
- Place rocks on north reef.
- Continue work on breakwater 1
- Carry out slipway rock bund.
- Complete remaining shingle nourishment digs

Public Relations

• Work to lay base of footpath to the church.